

Troubleshooting:

Problem: No video or audio on any receiver.

- Try this:**
- 1) Check CAT-5 connection from SVC-10 transmitter to the SVD-8.
 - 2) Check power on SVD-8 and SVC-10 transmitter.
 - 3) Check video/audio source power and connections to transmitter.

Problem: No video or audio on only one receiver.

- Try this:**
- 1) Check CAT-5 connection from SVD-8 to the SVC-10R receiver.
 - 2) Check power on SVC-10R receiver.
 - 3) Check for proper connections from the SVC-10R receiver to the TV.

Problem: Poor video quality at one location.

- Try this:**
- 1) Check CAT-5 connection from SVD-8 to the SVC-10R receiver.
 - 2) Check proper dial setting on the SVD-8 for that location.

Troubleshooting hints:

- Problems that appear at all locations are likely due to connection errors between the SVC-10 transmitter and the SVD-8.
- Problems that appear at only one location are likely due to connection errors between the SVD-8 and the SVC-10R receiver.
- Proper termination is key - verify the correct color codes at each end of the CAT-5 cable.

LIMITED WARRANTY STATEMENT

Linear LLC warrants this product to be free from defects in material and workmanship for 2 years. The time period will be measured using the date code labeled on the product. Linear LLC is not responsible for damage to the product resulting from the buyer's improper handling, stocking or warehousing of the product. Any implied warranty arising from the sale of the product including implied warranties of merchantability and fitness for purpose are limited. Linear LLC shall not be responsible for any losses, damages or expenses, whether direct, consequential, or incidental arising from the use or the inability to use the product. Some states and countries do not allow limitations or how long an implied warranty lasts or the exclusion or limitation or incidental or consequential damages, so the above exclusions may not apply. The Linear LLC warranty gives specific legal rights in addition to other rights, which may exist and vary from state to state and country to country.

The warranty is limited to repair or replacement of products returned, freight prepaid, to Linear LLC, there is NO PROVISION FOR LABOR COST OR OTHER REIMBURSEMENTS OF ANY KIND.


1. Failures due to product abuse, such as negligence, improper use, and electrical surge including damage from lightning, water damage or other damage due to natural disasters are not covered by the warranty. The most common form of product abuse is surge damage caused by lightning.
2. The warranty shall also be voided by any tampering with the date code, labels or other markings on the product.
3. Products that are damaged in transit to Linear LLC due to improper packaging or by the carrier (shipping company) will not be covered under the warranty. If the product was damaged or lost by the carrier, it is the sender's responsibility to create a claim against the carrier.
4. The user is responsible for all labor costs associated with removing, reinstalling and returning the product to Linear LLC.

Linear LLC, at its option, will repair or replace the defective product. Replacements will be made from B-Stock, if an exact replacement is not available, Linear LLC, at its option, will select the nearest equivalent product. The user is responsible for freight charges to Linear LLC. Linear LLC will return warranted repaired or replacements by UPS Ground or an equivalent service. A customer may pay the additional costs for second-day or next-day service.

All products returned for warranty service require a Return Product Authorization Number (RPA#). Contact Linear Technical Services at 1-800-421-1587 for an RPA# and other important details.



S-Video Distribution Module




Model SVD-8

Designed for
ChannelPlus and OpenHouse
structured wire grid systems.

Linear[®]

(760) 438-7000 USA & Canada (800) 996-5225
Toll Free FAX (800) 468-1340
www.channelplus.com

Typical Installation



SVD-8 Contents

- (1) SVD-8 S-Video Distribution Module
- (1) 15VDC power supply
- (2) Flat surface mounting ears
- (44) Location Labels

Wiring Modular Plug (T568A)

